DEPARTMENT OF THE ARMY TECHNICAL MANUAL

OPERATOR'S MANUAL

BORING MACHINE, ENGINE CYLINDER

(ROTTLER BORING BAR COMPANY,

MODEL NO. DA-1H)

(4910-473-6361)

This copy is a reprint which includes current pages from Change 1.

HEADQUARTERS, DEPARTMENT OF THE ARMY

NOVEMBER 1964

AGO 6567A

HEADQUARTERS DEPARTMENT OF THE ARMY WASHINGTON, D.C., 16 November 1964

TM 9-4910-437-10 is published for the information and use of all concerned.

By Order of the Secretary of the Army:

HAROLD K. JOHNSON, General, United States Army, Chief of Staff.

Official:

J. C. LAMBERT, Major General, United States Army, The Adjutant General.

Distribution:

Active Army: DCSLOG (1) CNGB (1) TSG (1) CofEngrs (6) CofSptS (2) CofT (1) CC-E (1) USCONARC (3) USAMC (12) USASMC (6) ARADCOM (2) ARADCOM Rgn (2) OS Maj Comd (1) OS Base Comd (1)

NG: None. *USAR*: None. For explanation of abbreviations used, see AR 320-50. LOGCOMD (3) Armies (3) except Second USA (2) Seventh USA (5) EUSA (5) Corps (2) USA Corps (2) USAAVCOM (10) USAWECOM (75) LXAD (2) LEAD (1) TEAD (16) Units org under fol TOE: 11-587 (2)

TAGO 6567A-Nov

HEADQUARTERS DEPARTMENT OF THE ARMY WASHINGTON, D.C. 28 November 1972

Operator Manual

BORING MACHINE, ENGINE CYLINDER:

(ROTTLER BORING BAR COMPANY,

MODEL NO. DA-1H)

(4910-473-6361)

This change is current as of 8 November 1972.

TM 9-4910-437-10, 16 November 1964, is changed as follows:

Page 19, (blank page). Add the following information:

CHANGE

No. 1

PARTS INCLUDED WITH END ITEM

Parts included with end item and considered a component or part of item configuration are listed in the following table. The part numbers listed are Rottler Boring Bar Company (Code 52014) numbers.

Description	Part number
BIT, CUTTER: carbide, RH	501-31
BIT, CUTTER carbide, R-8	501-59
BOLT SET, HOLD-DOWN: set of 3, 5/8-11 x 3-1/2, 4, and 5-1/2 in. Ig.	501-14
DRIVER, HEXAGON: screwdriver type	501-73
FINGER, CENTERING: 3-¼ in. lg., 4 per set	501-2
HANDLE, CRANK: hand feed	500-98
HOLD-DOWN CLAMP ASSEMBLY: c/o	
BODY, HOLD-DOWN:	501-16
SCREW, ADJUSTING: 3/8-18 THD x 3-¼ in. lg.	501-13

PARTS INCLUDED WITH END ITEM¾ Continued

Description	Part number
SCREW, ADJUSTING: 1 in. THD	501-11
WING, HOLD-DOWN: med	501-9
WING, HOLD-DOWN: short	501-10
HOLDER, TOOL: 2-¼ in., short	200-1-3
HOLDER, TOOL: 2-½ in., med.	200-1-4
HOLDER, TOOL: 3 in., lg.	200-1-5
HOLDER, TOOL: 3-9/16 in., extra lg.	200-1-6
HOOK, LIFT:	501-46
JIG, SHARPENING:	35
KEY, MICARTA:	500-62
MICROMETER:	501-42
MIKE, WRENCH:	501-43
NUT, THRUST: br	500-41
PULLER, TOOL HOLDER:	100-24
WASHER, HOLD-DOWN:	501-15
WRENCH, T-HANDLE:	501-12
WRENCH, TOOL HOLDER:	100-23

Page. 22, Appendix. Section II is suspended as follows:

(1) Source maint. and recov. code			(2)	(3)	(4)	(5) Qty. inc.	(6) Illustrations (a) (b)	
(a) Source	(b) Maint-	(c) Recov.	Federal Stock No.	Description	Unit of issue	in unit	Fig. No.	ltem No.
				BASIC ISSUE ITEMS LIST—SECTION II BIIL is a list in alphabetical sequence of items which are furnished with, and which must be turned in with, the end item				
С	O/C	_	5935-545-3886	ADAPTER, ELECTRICAL CONNECTOR: plastic dielectric, 2 fl parallel male contacts and ground lead w/term, one end, 2 fl parallel and 1 U female contact other end, ac/dc, 25-V, 15 amp (52014:501-65).	EA	1	1	15
С	O/C	R	NA	TOOL BOX: (52014:100-44).	EA	1	1	1

Section II. BASIC ISSUE ITEMS LIST

Federal stock number is being assigned for item marked NA and then numbers will be published at a later date.

Page 23, figure 1. Delete the following item numbers from figure 1; 2 through 14, and 16 through 18.

Page 24, figure 2. Deleted.

By Order of the Secretary of the Army:

Official:

VERNE L. BOWERS Major General, United States Army The Adjutant General

Distribution:

Active Army:

DCSLOG (1) COE (6) USACDC (2) CONARC (3) AMC (12) ARADCOM (2) ARADCOM Rgn (2) OS Maj Comd (1) OS Base Comd (1) LOGCOMD (3)

NG and USAR: None

For explanation of abbreviations used, see AR 310-50.

CREIGHTON W. ABRAMS General, United States Army Chief of Staff

Armies (3) except Seventh (5) Eighth (5) USAAVSCOM (10) USAWECOM (10) LBAD (2) LEAD (1) TEAD (16) Units org under fol TOE: 11-587 (2)

DESCRIPTION

The Model DA-1 bar is a portable precision boring unit, complete with single point tooling and accessories for standard engine reboring work. All feeds and traverses are power operated and controlled from the upper gear housing unit, as auxiliary hand travel is located at the base of the feed screw. Power is furnished by end mounted AC single phase 110-220 Volt General Electric motor of ³/₄ HP, 3 phase. A quick change lever selects two spindle speeds.

Gear housings are aluminum alloy in order to incorporate the lightest possible weight without sacrificing rigidity.

NOTE

When bar is shipped from factory, the machined surfaces are protected with rust veto. After uncrating, use clean cloth dampened with kerosene and remove the protective oil.

CONTROLS

We suggest, before attempting to bore, you clamp the bar over an open area and actuate the controls to become familiar with them.

1. Feed lever is latching lever on side of bar. Press down until lever latches to engage cutting feed. To disengage press (3) feed release arm which will unlatch lever and allow it to return to neutral position. Lift feed lever (2) until it latches to engage rapid return travel. Bar will automatically return to neutral upon reaching top of travel. If you wish to return bar to neutral while it is in rapid up travel, again press (3) feed release which will unlatch lever and allow it to return to neutral position.

You will note stop rod that is held in base casting by thumb screw has a cone shaped end which will release cutting feed when it contacts lever. This is most conveniently raised up and locked by thumbscrew in proper position on completion of first. bore cut. This rod should not be used to hold close tolerance shoulders. Optional equipment for this is available.

2. The fast down travel lever is located next to feed lever. Check feed lever to see that it is in neutral position before actuating. Lever should be pulled down quickly and firmly and not allowed to ratchet. Control is spring loaded and will release when you release pressure.

3. Spindle clutch control is located opposite side of feed lever. A rapid down movement will engage spindle rotation and a reverse action will disengage. In that this is a jaw clutch we recommend stopping the motor or jogging the motor to engage clutch on the high RPM of the machine. Standard procedure is to throw out clutch upon completion of the bore. Align marks by turning spindle knob, then reverse travel.

The small knob on top of the upper housing may be used for manually turning spindle when necessary, this knob is also used for centering.

4. 2-½" manual travel is actuated by rotating handle attached to spline at top of base. This travel should always be left in full up position after using bar. Normal procedure is to rapid travel or feed bar to point requiring manual travel.

If back feeding is necessary run hand travel down first and then rapid travel down to where tool can be inserted.

5. Speed control is operated by pulling knob at motor gear housing and raising for low speed and lowering for high. These may be changed when bar is running.

OPERATING INSTRUCTION - AUTOMOTIVE

We recommend, particularly for operators unfamiliar with the DA-1 bar, to practice on a junk block in order to become acquainted with all controls and details connected with the use of the machine.

1. Carefully clean and file off high spots, thread burrs, etc. on top of cylinder blocks.

2. Measure each cylinder. Determine the amount of metal to be removed from the measurement of cylinder which shows the most wear.

3. Insert the proper size wing in the hold down clamp for the diameter of cylinder and adjust hold down length so that 5/8" anchoring screw will have at least a 3/8" length of thread holding. After placing through bar base, reach through cylinder and make sure there is an adequate square surface where you intend to set hold down. Beware of fillets and chamfers around clamping area. In blocks which have relief for connecting rod clearance the hold down lug will most often straddle the relief with adequate holding surface on each corner. It is convenient to insert one of the 5/8" bolts in the hold down to hold it while expanding the wing with the T wrench. Use light tension on T wrench. Excessive tightening will result in distortion of bore and marks in finished cylinders. In many blocks it is possible to utilize the stud holes to anchor the bar.

In any event attempt to set the hold down device so the boring bar can be pivoted to bore adjacent cylinders on either side and hold down bolt is as close to spindle as practical.

Check also to make sure there is good contact of boring bar base and block on all sides of hold down. If this is questionable, it is advisable to use additional clamps after centering bar such as milling machine type clamp on the steps of the base.

Place the bar with spindle over the hole to be bored and insert the bolt in the hold down without tightening. Check to make sure tool holder is not in bar and centering fingers are not extended.

Start motor and rapid travel bar into cylinder for centering. It is usually desirable to locate fingers just under the ring wear ridge. Bear in mind that No. 2 and 4 centering fingers are slightly higher than others and must be under the ridge. The best method of centering when little stock is left for clean up is to rotate spindle with top knob so that 2 fingers straddle the greatest wear under the ridge. These wear pockets generally occur in line with the block.

After locating fingers properly, extend them by turning top centering knob and exert tension on the knob while tightening hold down bolt. Do not over tighten. Approximately 25 lb. tension on 8" wrench is adequate. Before tightening hold down bolt it is advisable to rock bar slightly to make sure fingers are making positive contact with cylinder wall. Retract fingers into head and return bar to up position by latching feed lever in up position.

4. It is necessary to change fingers to accommodate the entire range. The most convenient method is to lay-bar on bench, control side up. Run spindle down a few inches with the rapid down travel, shut off motor and run the fingers out with top knob. Insert the other fingers in the slots being careful to match the numbers on the fingers to the numbers on the slots. Hold all fingers inward with one hand and rotate centering knob—first to right and then to left retracting them into the head. Check to see that all fingers are retracted equally and return bar to up position.

SHARPENING CUTTER

5. The performance of your boring bar and quality of work it will do is almost entirely dependent on the care of the cutting tool. It is the most frequent cause-of size and finish problems in boring.

To sharpen the carbide bit insert tool holder in sharpening jig slot. Insert the jig shank in the hole provided in the upper housing and sharpen bit on the small diamond wheel provided on the large knob. Always make sure you sharpen the tool on the side of the diamond that is running toward the top face of the bit. Sharpening on the wrong side can readily chip the point. When sharpening use very light pressure, moving the tool back and forth across the diamond wheel to improve cutting and prevent grooving of diamond. After sharpening a number of times dress excess steel away from carbide on grinding wheel. This will facilitate use of chip remover hoods and make for quicker sharpening. Diamond wheel is designed for carbide only. Steel tends to load it. (See back page for sharpening instructions.)

BORING

If tool is properly sharpened place cutter and proper tool holder in micrometer. Hold tool bit lightly against mike anvil and loosen Allen screw with wing wrench. Gently let tool holder slide back to make contact with micrometer spindle. This procedure will prevent chipping carbide. This micrometer is .050 to a revolution rather than .025 as on a conventional mike. Set mike to size you wish to bore and tighten set screw lightly. Back off mike and tighten set screw. Here again excessive tightening only tends to nick mike anvil and make future setting difficult. After tightening recheck size.

Make sure tool holder and tool holder slot in head are free from dirt. Insert tool in slot making sure it is completely back and latched. Lock set screw, for heavy cuts only, with socket type screw driver provided with tools.

<u>NOTE</u>

For cast iron boring the motor speed control is placed in the down or fast (305 RPM) position for normal cuts. For extremely heavy cuts, the control should be in the up or slow speed (80 RPM) position.

For hard sleeve boring the motor speed control should always be in the up or slow speed (80 RPM) position.

BORING

Engage spindle clutch and latch feed lever in down position. When bar has completed boring, set stop rod so lever will be thrown into neutral position. Stop rod will then be set for the other holes on the same cylinder block.

Disengage spindle clutch. Turn spindle to align marks at knob and latch feed lever in up position. Turn off motor. Remove tool holder with tool puller. (Always remove tool holder after boring.) Loosen anchor bolt and proceed to next cylinder. If bore is to be chamfered with bar this should be done before loosening anchor bolt.

CHAMFERING

A special tool is available for chamfering. Tool may be set by either inserting in head and approximating setting or place in mike and set approximately .100 over bore size. Chamfering may be done either by using feed and releasing when adequate chamfer has been developed or by use of hand feed.

AUTOMOTIVE

DA-1 Boring Bar - OPERATING INSTRUCTIONS

CENTERING FINGERS

Centering fingers are adequate to center the new bore within .002 of the centering of old bore; providing the old bore is reasonably round and if you follow operating instructions properly. Centering fingers can be lapped periodically to obtain near perfect centering. Use the following procedure in-an undersize bore or junk block.

TO LAP FINGERS

- 1. Bore hole and remove cutter but do not <u>unclamp bar</u>.
- 2. Rapid traverse bar down into hole.
- 3. Extend fingers and exert pressure on them against cylinder wall while rotating inner spindle knob to left by hand (counter-clockwise).
- 4. After rubbing, examine points on all fingers to make sure they are all making contact.

MICROMETER

Your boring bar micrometer, as with any other measuring tool, should be used delicately and with care to be assured of the greatest accuracy. Particular attention should be paid to inserting the tool in micrometer without allowing tool bit to snap into mike anvil. Care should be used in the method of lightly locking tool bit before tightening.

After a period of use you will note that the tool bit tip will force a depression in the micrometer anvil. This, of course, will result in inconsistent sizes, particularly after resharpening the bit. Periodically we would recommend turning the anvil slightly and finally end for end so that a flat surface is exposed to the tool bit tip.

SETTING MICROMETER

- 1. Bore a hole.
- 2. Remove tool holder and bit and place in mike.
- 3. Adjust mike so that it reads the same size as the hole you have bored. Small variations may be made by turning the mike sleeve with spanner wrench provided. Larger changes should be made by moving the anvil.

DIAMOND WHEEL

Care of Diamond Sharpening Disk

If the diamond disk is handled with care it will provide many years of service.

Occasionally diamond surface can load up if steel part of tool bit is not ground back as sharpening instructions indicate. To clean disk apply a small amount of solvent or thinner and rub off.

LUBRICATION

Upper Housing should be packed with 5 parts Union Oil Ebon cup light grease, 1 part 30 weight machine oil approximately every 25,000 boring cycles.

Motor gear housing should be re-packed with 3 parts Ebon cup light grease, 1 part 30 weight machine oil approximately every 50,000 boring cycles. A very occasional drop of oil in the motor gear pot (socket head screw near bottom) will help maintain lubrication at right consistency.

Every 2 days of operation fitting at top of spindle should be lubricated with Ebon cup light grease for top inner spindle bearing.

Socket set screw in key way of spindle should be removed and a few drops of oil put in approximately every 500 bores. Do not over fill.

DA-1 BORING BAR

ADJUSTMENT OF OUTER SPINDLE

Main spindle bearings are tapered split cast iron rings held in seat by adjustment nut. Tension on bearings is normally adequate to require no adjustment for many boring cycles.

Caution should be used in adjusting these bearings in order to avoid a too tight spindle which only serves to wear out machine and make control operation difficult. If it should be necessary to adjust proceed as follows:

Upper bearing is adjusted by removing felt retaining nut at top of base forcing felt up and adjust nut with punch.

For lower bearing first back off friction screw (3/8" and 8-32 at bottom spindle bearing). Then remove felt retainer at bottom of base and turn nut with punch.

- 1. Place and clamp bar over hole or overhang so spindle can be run down. Loosen both adjusting nuts and set screw.
- 2. Tighten upper bearing until additional pressure is required to operate hand feed.

Repeat this sequence on lower bearing taking care that hand feed operates only slightly tighter.

3. Traverse bar at all points-of travel and make sure hand feed works easily. Spindles are ground slightly tapered to secure maximum rigidity at lower limits of travel where it is most required.

4. Spindle adjustment may also be checked by feeding spindle down and pulling slack out of feed mechanism by forcing down upper housing. Pressure required should be 50-75 lbs.

5. Reset friction screw (3/8" set screw) tight and back off 1/10 turn.

DA-1 BORING BAR

ADJUSTMENT OF INNER SPINDLE

- 1. Remove two screws and small cover on back side of upper housing.
- 2. Remove pin restricting up travel of spindle clutch lever and move lever to full up position.

3. Insert pin (diam. .180 or less) in one of the holes provided in the O D of take up nut. (See inner spindle nut.) Hold spindle knob with one hand and turn take up nut to right (clockwise). You will note the net ratchets in notches as you take up. Take up until spindle is tight and back off ³/₄ to 1-¹/₂ notches. Run bar on high speed making sure there is only slight heating at bottom of spindle. If heat is excessive, back off one notch further.

4. Replace cover and pin.

EXCESSIVE LOADS

NOTE

If excessive loads are imposed on your Model DA-1 Boring Bar.

1. Thrust loads - If bar is fed or rapid-traveled into object that imposes an excessive thrust load on spindle, the Brass Thrust Nut Part No. 5100-78 will probably be sheared and require replacing. This accident could happen with spindle either rotating or stationary.

The effect of this will be for the bar to continue to run but with no feed or down travel working. If bar is left in feed or down travel, drive spline will be pulled completely out of mesh at which point motor will continue to run but feed screw will not turn at all.

2. Radial loads - If bar has a tool in cutter head that turns into an object an excessive radial shock will be imposed on spindle and will probably shear motor drive key No. 500-62. This would likely happen only when spindle drive clutch is in.

The immediate effect of this will be for the motor only to run not turning any visible parts of the boring bar. A movement of the speed change lever will indicate the lower gear box is entirely inoperative.

REMOVAL OF MOTOR FIELD ASSEMBLY

NOTE

This is the only disassembly required to replace Micarta Motor Drive Key in cases of excessive radial load on machine spindle.

SECTION B

Remove 4 long motor screws and lift off motor field assembly. Be careful not to lose spring washer on top bearing, and replace properly in reassembly.

Lay blocks on bottom end bell and pry up stator out of drive to remove stator.

DISASSEMBLY OF DA-1 MOTOR HOUSING

NOTE

Motor housing may be removed without disassembly of upper housing and feed screw.

SECTION A-1

Remove 2 hex socket screws on bottom of 500-97 hand feed bracket and 2 screws holding 500-06 plate to 500-70 housing. Turn out (counter clockwise) bevel gear.

Remove 4 flat head hex socket screws in 500-70 housing. Lift out screw, or if upper housing is still intact hold in rapid down lever, 500-30, and rotate screw counter clockwise until feed screw is clear of motor unit. On reassembly it may be necessary to rotate motor and screw, using care in aligning spline in gear to match screw spline. Make sure threaded key does not jam on entering slot.

REMOVAL OF FEED SLEEVE AND BEARING

NOTE

For removal of brass nut only. (This disassembly is not necessary to remove motor housing).

SECTION A-2

Remove snap ring set screw 5002-185, and press sleeve assembly, 500-73, off bearing. Back out socket set screw from brass thrust nut and screw off nut. Bearing may now be removed from shaft.

REMOVAL OF MOTOR HOUSING

To remove motor housing back off 2 base set screw supports and take out 4 bolts in housing flange. In reassembly motor alignment must be checked after screw sleeve is in place before flange bolts are permanently locked. Use surface plate over screw and spindle.

To disassemble housing, remove pin and 6 Filluster screws and bottom screw in middle of bottom of gear pot. Remove 2 set screws on speed shifter lever.

Tap lightly on motor pinion, 500-54, and screw drive gear, 500-69, and housing will come apart. Pinion shaft, 500-68, with clutch and gears may be tapped out with small punch through center hole in bottom of gear pot.

DISASSEMBLY OF DA-1 UPPER HOUSING & SPINDLE REMOVAL

Remove 500-16 knob by releasing socket set screw. Remove 500-17 knob by releasing socket set screw. (On automotive units you may then draw out centering rod). Unscrew spindle clutch lever stop pin, 500-3. Raise lever to extreme top, which will allow removal of countersunk screw and lever assembly. Remove cap screw to disassemble trip lever, 500-35.

CAUTION

Do not lose trip spring.

Remove 6 screws holding upper housing sections together and lift off upper lid, 500-22.

Now parts shifting lever, 500-38, with springs may be removed along with 500-25 upper fast return gear with plunger and spring, spindle clutch and key, 500-3, ball bearing with take-up spring, 500-18, (be sure spring is reassembled properly), sleeve gear, 500-1, feed nut, 500-2, and feed gear with thrust washer, 500-8.

If the bar is in a vertical spindle position we suggest you place something under the spindle nose to prevent lubrication from running out and then remove 500-5 spindle nut. Nut can be started off through adjusting access hold and then hand turned. Now drive gear, 500-6, may be worked off along with 500-4 spacer and Woodruff key.

Inner spindle may now be removed. Ball bearing type will have to be lightly driven out.

2" cap screws in upper housing should be removed and housing may be driven off spindle. Heat on housing will simplify removal of this sweat fit.

Lift off of feed screw.

Nut should be removed from 500-29 shaft and shaft may be pressed out with gear.

500-19 long gear with radial and thrust bearings may be removed along with oil seal.


Extreme care should be taken when removing long gear out of seal or seal out of housing. Seal is fragile and garter spring will come out easily.

When reassembling, open seal as long gear is pushed in to prevent garter spring from snapping out.


RAPID RETURN TRAVERSE

If the boring bar should ever fail or hesitate to return to top of travel when shift lever is lifted and latched, the following procedure may be used to adjust return traverse clutches.


- 1. Run bar down into hole a few inches.
- 2. Loosen set screw at top of upper housing. (Refer SC Sec. A-A.)
- This will allow you to tap rapid return tumbler assembly, (Top of shaft located on top of upper housing opposite spindle side) down slightly which will result in deeper engagement of clutches. Adjust tumbler shaft so that when shift lever is in neutral, clutches do not clatter. Clutches should engage immediately upon latching lever.
- 4. Tighten set screw to relock shaft. Check to see adjustment has not been changed by set screw.




SECTION A-A




SECTION B-B









DETAIL F




DETAIL E



DETAIL G



SHARPENING OF THE CUTTING TOOL



501-31 CAST IRON BIT

The performance of your boring bar and the quality of work it will do is almost entirely dependent on the care of the cutting tool.

In the accompanying sketch, letters A, B, D correspond to the letters indicated on your sharpening jig, in other words, when your jig is set in the A position it will sharpen the "A" land as shown in the sketch.

The most critical point of this sharpening is the width of the "B" land (as indicated by the diagonal line shading). This width should be maintained at about .015 to .020 or 1/64". This width is held by cutting back the D land as required.

In the event your bar chatters or bores a rough finish at the bottom of the cylinder, it is very probable this "B" land is too wide.

The A cutting land is not critical as to width but should be maintained in good condition to obtain free cutting, particularly on heavy cuts.

The top surface of the bit is finely finished at the factory and requires no further resurfacing. This also means no honing or in any way attempting to break off the chip that sometimes seems to be apparent. The practice of doing these things will inevitably result in poor surface finish and impair the accuracy of the machine.

The frequency of sharpening the bit required will vary depending on the type of iron being bored. A six cylinder block can sometimes be bored without resharpening, and often it is advisable to touch up the cutting tool on every hole for best results.

501-59 HARD SLEEVE BIT

The hard sleeve tool bit is sharpened like the cast iron bit except the "H" land is used in place of the "B" land.

Section I. INTRODUCTION

1. General

This appendix is a list of basic issue items. It is composed of those items which make up the major end item of equipment and the operator's tools and equipment that are issued with the equipment and are required for stockage.

2. Requisition Notes

a. Repair Part Identified by Federal Stock Number.

- (1) If the exact item requisitioned is not furnished, or if other action is necessary, the exact nature of the action taken by the commodity command will be indicated by standard symbols on prescribed forms.
- (2) When requisitioning an item, the requesting agency will order the listed item. However, the commodity command will take necessary action to issue the exhaust stock item until stock is exhausted, whether it be an individual item, kit, set, or assembly.
- (3) Requisition for replacement of items that are the responsibility of commodity commands will be submitted to the commodity command indicated in column la, Materiel Code Number.

b. Part To Which FSN Has Not Been Assigned. When requisitioning a C source (local procurement) item identified by a manufacturer's part number, it is mandatory that the following information be furnished the supply officer:

- (1) Manufacturer's code number (5 digit number preceding the colon in descriptive column).
- Manufacturer's part number (the number, and sometimes letters, following the colon ((1) above). Dashes, 20 commas, or

other marks must be included exactly as listed.

- (3) Nomenclature exactly as listed herein, including dimensions, if necessary.
- (4) Name of manufacturer of end item (from cover of TM or manufacturer's name plate).
- (5) Federal stock number of the end item (from TM).
- (6) Manufacturer's model number (from TM or name/data plate, preferably name/data plate).
- (7) Manufacturer's serial number (from name/data plate).
- (8) Any other information such as type, frame number, and electrical characteristics, if applicable.
- (9) If DD Form 1348 is used, fill in all blocks except 4, 5, 6, and Remarks field in accordance with AR 725-50.

Complete form as follows:

- (a) In blocks 4, 5, and 6, list manufacturer's code and part number (as listed in description column).
- (b) In Remarks field, list noun name (repair part), end item application (FSN of end item), manufacturer, model number (end item), serial number (end item), and any other pertinent information such as frame number, type, etc.

3. Explanation of Columns

a. Source, Maintenance, and Recoverability Code (Col. 1).

 Materiel numerical code (Col. 1 a). This column indicates the responsible commodity command for the materiel. The commodity commands responsible for supply of items in this list is:

Code	Type materiel
9	Ordinance

(2) Source (col. 1b). This column indicates the selection status and source for the listed item. Source code used in this list is:

Code C Explanation Obtain through local procurement. If not obtainable from local procurement, requisition, through normal supply channels supporting with а statement of nonavailability from local procurement.

(3) *Maintenance level* (col. 1c). This column indicated the category of maintenance authorized to install the listed item. Maintenance level code used in this list is:

> Code Explanation O/C Operator or crew maintenance.

(4) Recoverability (col. 1d). This column indicates whether unserviceable items should be returned for recovery or salvage. When no code is indicated, the item will be considered expendable. Recoverability code used in the list is:

Code	Explanation
R	Items which are
	economically repairable
	at direct and general
	support maintenance
	activities and are
	normally furnished by
	supply on an exchange basis.

b. *Federal Stock Number* (col. 2). This column indicated the Federal stock number which has been assigned by the Cataloging Division, Defense Logistics Services Center.

AGO 6567 A

c. *Description* (col. 3). This column indicates the Federal item name (shown in capital letters) and any additional description required for supply operations. The manufacturer's code and part number are also included for reference.

d. *Unit of Issue* (col. 4). This column indicated the quantity to be requisioned.

e. *Quantity Authorized* (col. 5). This column indicated the quantity of the listed item authorized for stockage to constitute the prescribed load.

f. *Illustration* (col. 6). This column indicates the figure number of the illustration that depicts the listed item. When more than one item appears on an illustration, the item number is also indicated.

4. Abbreviations and Symbols

ac	
amp	ampere (s)
br	brass
c/o	consist of
dc	direct current
fl	flat
in	inch (es)
lg	long
med	medium
term	terminal
v	volt (s)
w	with
х	by (as in 2 x 4)

5. Suggestions and Recommendations

The direct reporting by the individual user, of errors, omissions, and recommendations for improving this manual is authorized and encouraged. DA Form 2028 (Recommended Changes to DA Publications) will be used for reporting these improvements. This form will be completed in triplicate using pencil, pen, or typewriter. The original and one copy will be forwarded direct to:

> Commanding General Headquarters, U.S. Army Weapons Command ATTN: AMSWE-SMM-P Rock Island, III. 61202

Section II. BASIC ISSUE ITEMS

(a)	Recovei (b)	nance, a rability Co (c)	ode			1			ation
ateriel-		(c)							
	Source		(d)					(a)	(b)
		Mainten ance level	Recover- ability ability	Federal stock No.	Description	Unit of issue	Quantity Incorpo- rated in unit	Figure Number	ltem Numbe
			R	4910-443-6361	MAJOR COMBINATION The following item is to be requisitioned for initial issue only. BORING MACHINE, ENGINE CYLINDER: (52014 :DA-1H). COMPONENTS OF MAJOR COMBINATION None authorized REPAIR PARTS None authorized	ea	1	_	
9	С	O/C		5935-545-3886	TOOLS AND EQUIPMENT FOR: BORING MACHINE, ENGINE CYLINDER (52014 :DA-H) ADAPTER, ELECTRICAL CONNECTOR: plastic dielectric, 2 fl parallel male contacts and ground lead w/term. one end, 2 fl parallel and 1 U female contact other end, ac/dc, 25-V, 15 amp (52014:501-65).	ea	1	1	15
9	С	O/C			BIT, CUTTER: carbide, R-8 (52014:501-59)	ea	1	1	7
9	č	O/C			BIT, CUTTER: carbide, R-H (52014:501-31)	ea	1	1	8
9	Č	O/C			BOLT SET, HOLD-DOWN: set of 3, 5/8-11 x 31/2, 4, and 51/2 in. Ig (52014:501-14).	ea	1	2	2
9	С	O/C			COMPOUND, SHARPENING: (52014:100)	jr	1	1	14
9	С	O/C			DRIVER, HEXAGON: screwdriver type (52014:501 73).	ea	1	1	18
9	С	O/C	R		FINGER, CENTERING: 3Y1 in. lg, 4 per set (52014: 501-2).	st	1	1	6
9	С	O/C	R		HANDLE, CRANK: hand feed (52014:500-98) HOLD-DOWN CLAMP ASSEMBLY: c/o	ea	1	2	10
9	С	O/C	R		BODY, HOLD-DOWN: (52014:501-16)	ea	1	2	5
9	С	O/C			SCREW, ADJUSTING:. 3/8-18 in. THD x 3 1/4 in. Ig (52014:501-13).	ea	1	2	4
9	С	O/C			SCREW, ADJUSTING: 1 in. THD (52014:501-11)	ea	1	2	3
9	С	O/C			WING, HOLD-DOWN: med (52014:501-9)	ea	1	2	7
9	С	O/C			WING, HOLD-DOWN: short (52014:501-10)	ea	1	2	6
9	С	O/C	R		HOLDER, TOOL: 2 1/4 in., short (52014:200-1-3)	ea	1	1	5
9	С	O/C	R		HOLDER, TOOL: 2 1/2 in., med (52014:200-1-4)	ea		1	4
8	C C	0/C 0/C	R		HOLDER, TOOL: 3 in., Ig (52014:200-1-5) HOLDER, TOOL: 3 9/16 in., extra Ig (52014:200-1-6)	ea		1	3 2
9 9	c	0/C	R R		HOLDER, TOOL: 3 9/16 III., exita ig (52014.200-1-6) HOOK, LIFT: (52014:501-46)	ea ea		2	2
9	c	0/C	R		JIG, SHARPENING: (52014:35)	ea		1	16
9	č	O/C			KEY, MICARTA: (52014:500-62)	ea		1	10
9	С	O/C	R		MICROMETER: (52014:501-42)	ea	1	1	13
9	С	O/C			NUT, THRUST: br (52014:600-41)	ea	1	1	9
9	С	O/C			PULLER, TOOL HOLDER: (52014:100-24)	ea	1	1	17
9	С	O/C	R		TOOL BOX: (52014:100-24)	ea		1	1
9	C	0/C			WASHER, HOLD-DOWN: (52014:501-15)	ea	3	2	1
9 9	C C	O/C O/C			WRENCH, T-HANDLE: (52014:501-12) WRENCH, TOOL HOLDER: (52014:100-23)	ea ea		2 1	9 11
3	0	0,0			WINEMON, TOOL HOLDER. (32014.100-23)			I	11




Figure 1. Tools and equipment for engine cylinder boring machine.

AGO 6667A




Figure 2. Tools and equipment for engine cylinder boring machine.

AGO 6567A

*U.S GOVERNMENT PRINTING OFFICE: 1993 - 342-421/63046

/	RECOMMENDED CHANGES TO EQUIPMENT TECHNICAL PUBLICATIONS						
\Box	5.				SOMET	NING	B WRONG WITH PUBLICATION
		DC CA	REFULLY	T IT ON T TEAR IT (HIS FORM. DUT, FOLD IT	FROM	: (PRINT YOUR UNIT'S COMPLETE ADDRESS)
		P AN	D DROP I	I IN IHE I	MAIL.		
PUBLICAT	TION NUMBE	ĒR			PUBLICATION DA	ATE	PUBLICATION TITLE
BE EXAC	t Pin-PC	DINT WHER	re it is	IN THI	S SPACE, TEI	L WH	AT IS WRONG
PAGE NO.	PARA- GRAPH	FIGURE NO.	TABLE NO.	AND W	VHAT SHOULI	D BE D	ONE ABOUT IT.
PRINTED	NAME, GRA	DE OR TITL	E AND TELE	EPHONE NU	JMBER	SIGN HE	RE
	DRM 20	28-2		EVIOUS EDI E OBSOLET		RE	SIF YOUR OUTFIT WANTS TO KNOW ABOUT YOUR COMMENDATION MAKE A CARBON COPY OF THIS ID GIVE IT TO YOUR HEADQUARTERS.

The Metric System and Equivalents

Linear Measure

- 1 centimeter = 10 millimeters = .39 inch
- 1 decimeter = 10 centimeters = 3.94 inches
- 1 meter = 10 decimeters = 39.37 inches
- 1 dekameter = 10 meters = 32.8 feet
- 1 hectometer = 10 dekameters = 328.08 feet
- 1 kilometer = 10 hectometers = 3,280.8 feet

Weights

- 1 centigram = 10 milligrams = .15 grain
- 1 decigram = 10 centigrams = 1.54 grains
- 1 gram = 10 decigram = .035 ounce
- 1 decagram = 10 grams = .35 ounce
- 1 hectogram = 10 decagrams = 3.52 ounces
- 1 kilogram = 10 hectograms = 2.2 pounds
- 1 quintal = 100 kilograms = 220.46 pounds 1 metric ton = 10 quintals = 1.1 short tons

Liquid Measure

- 1 centiliter = 10 milliters = .34 fl. ounce
- 1 deciliter = 10 centiliters = 3.38 fl. ounces
- 1 liter = 10 deciliters = 33.81 fl. ounces 1 dekaliter = 10 liters = 2.64 gallons
- 1 hectoliter = 10 dekaliters = 26.42 gallons
- 1 kiloliter = 10 hectoliters = 264.18 gallons

Square Measure

- 1 sq. centimeter = 100 sq. millimeters = .155 sq. inch
- 1 sq. decimeter = 100 sq. centimeters = 15.5 sq. inches
- 1 sq. meter (centare) = 100 sq. decimeters = 10.76 sq. feet
- 1 sq. dekameter (are) = 100 sq. meters = 1,076.4 sq. feet 1 sq. hectometer (hectare) = 100 sq. dekameters = 2.47 acres
- 1 sq. kilometer = 100 sq. hectometers = .386 sq. mile

Cubic Measure

- 1 cu. centimeter = 1000 cu. millimeters = .06 cu. inch
- 1 cu. decimeter = 1000 cu. centimeters = 61.02 cu. inches
- 1 cu. meter = 1000 cu. decimeters = 35.31 cu. feet

Approximate Conversion Factors

To change	То	Multiply by	To change	То	Multiply by
inches	centimeters	2.540	ounce-inches	Newton-meters	.007062
feet	meters	.305	centimeters	inches	.394
yards	meters	.914	meters	feet	3.280
miles	kilometers	1.609	meters	yards	1.094
square inches	square centimeters	6.451	kilometers	miles	.621
square feet	square meters	.093	square centimeters	square inches	.155
square yards	square meters	.836	square meters	square feet	10.764
square miles	square kilometers	2.590	square meters	square yards	1.196
acres	square hectometers	.405	square kilometers	square miles	.386
cubic feet	cubic meters	.028	square hectometers	acres	2.471
cubic yards	cubic meters	.765	cubic meters	cubic feet	35.315
fluid ounces	milliliters	29,573	cubic meters	cubic yards	1.308
pints	liters	.473	milliliters	fluid ounces	.034
, quarts	liters	.946	liters	pints	2.113
gallons	liters	3.785	liters	quarts	1.057
ounces	grams	28.349	liters	gallons	.264
pounds	kilograms	.454	grams	ounces	.035
short tons	metric tons	.907	kilograms	pounds	2.205
pound-feet	Newton-meters	1.356	metric tons	short tons	1.102
, pound-inches	Newton-meters	.11296			

Temperature (Exact)

°F	Fahrenheit	5/9 (after	Celsius	°C
	temperature	subtracting 32)	temperature	

PIN: 006036-001

This fine document...

Was brought to you by me:



Liberated Manuals -- free army and government manuals

Why do I do it? I am tired of sleazy CD-ROM sellers, who take publicly available information, slap "watermarks" and other junk on it, and sell it. Those masters of search engine manipulation make sure that their sites that sell free information, come up first in search engines. They did not create it... They did not even scan it... Why should they get your money? Why are not letting you give those free manuals to your friends?

I am setting this document FREE. This document was made by the US Government and is NOT protected by Copyright. Feel free to share, republish, sell and so on.

I am not asking you for donations, fees or handouts. If you can, please provide a link to liberatedmanuals.com, so that free manuals come up first in search engines:

<A HREF=<u>http://www.liberatedmanuals.com/</u>>Free Military and Government Manuals

Sincerely
Igor Chudov
<u>http://igor.chudov.com/</u>
Chicago Machinery Movers